

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FH803
NNW
> 1
1.113 mi.
5879 ft.

INTERSECTION ON ROAD
AVENUE U & 86TH ST
BROOKLYN, NY

NY Spills **S110539983**
N/A

Site 1 of 3 in cluster FH

Relative:
Higher

Actual:
12 ft.

SPILLS:

Name: INTERSECTION ON ROAD
Address: AVENUE U & 86TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1006908 / 2010-10-05
Facility ID: 1006908
Facility Type: ER
DER Facility ID: 395297
Site ID: 440288
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2010-09-27
Investigator: smsanges
Referred To: Not reported
Reported to Dept: 2010-09-27
CID: Not reported
Water Affected: Not reported

Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-09-27
Spill Record Last Update: 2010-10-05
Spiller Name: Not reported
Spiller Company: NYC TRANSIT
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CLAIRE SAMMON
DEC Memo: "heavy rain washed the fluid into the storm drain. DEP notified"
Remarks: "cleanup done - weather cleaned up and washed out to sewer - bus awaiting tow"

All Materials:

Site ID: 440288
Operable Unit ID: 1190904
Operable Unit: 01
Material ID: 2185991
Material Code: 0021
Material Name: transmission fluid
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported